

File

LN 1806

17 January 1964

STATINTL

To:

Fr:

Subject: Service Bulletin HP-8191-SB8

1. Purpose of subject bulletin is self-explanatory. Contractor drawing has been changed to reflect this action, and all programmers processed for IRAN subsequent to this date will have the diodes removed.

2. Recommend release of this bulletin to implement change in field at earliest convenience. Recent evaluation reports indicate occasional movement in 1L position during exposure may be due to this condition.

STATINTL

AJB:jdj

Enc.